



F-5F Mat. 4502

Repair Proposal





Table of Contents / Description of Damages

A: Forward Fuselage bulkhead: Repair

B: Forward Fuselage station 47.65-87.5

2: Fuselage Section lower 47.5-87.5

A: Parts List

B: 18-10360

C: 14-10780 bulkhead

D: 14-10781 bulkhead

E: 18-10368 fs4750

F: Intercoastal

G: 18-10370

H: 18-10372

I: 18-10374

J: 18-10375

K: 18-10376 former lower

L: 18-10377

M: 18-10378

N: 18-10380

O: 18-10381

P: 18-10384

Q: 18-10385

R: Fasteners

S: Fixtures

T: Nose landing gear door

U: Repair/replace nose landing gear door

V: Repair/refurbish nose landing gear

W: Nose wheel steering actuator

X: Nose Landing Gear 14-41600





Summary



FAM aircraft 4502 suffered damages to nose of aircraft at FS 47.5 to 87.5 due to failure of nose landing gear that collapsed during taxi on runway. The radome was badly damaged as well as the nose landing gear door. The forward fuselage suffered damages to the lower structure consisting of 18-10360 assembly drawings. COC inspected the aircraft at Esquadron 401 on July 28, 2021 and determined the that the aircraft can be successfully repaired. COC inspected the PDM logbooks that document the condition of the aircraft as very good with no findings of corrosion or stress cracking of wing, fuselage and upper and lower longerons. This proposal provides the most cost effective and quickest program to return this aircraft to flight. COC will produce a complete 'Repair Kit' and will provide training, if needed, for the FAM to perform the repairs.





Current Condition of F-5F Mat. 4502



Major damage to lower forward fuselage but damage is limited to FS 47.5 to 87.5. There are no signs of damage past FS 87.5. The aircraft is fully repairable.









Current Condition of F-5F Mat. 4502



The damage requires that the entire lower section of the fuselage FS47.5 to 87.5 be replaced with new parts.



The upper section of the assembly is undamaged. The bulkhead at 47.5 needs replacement









Replace Nose Wheel Landing Gear Door











Repair, Refurbish Nose Landing Gear and Overhaul Steering Actuator



COC will disassemble nose landing gear, perform a complete inspection and rebuild nose landing gear.



Steering Actuator will be overhauled.









Price Proposal is divided into 4 sections.







4. Inspection of Fuselage Attach Section of Nose Landing Gear.



COC Lower Fuselage Repair Kit



Total Price: \$650,000.00 USD

Includes:



- Work Cards (Instructions in steps for disassembly and reassembly)

- Spare parts to replace all damaged parts.

- Fasteners, hardware, shims, etc.

NOTE: Cost for producing one (1) piece each for Northrop F-5F is very costly, therefore, pricing reflects this cost driver.





Nose Landing Gear Door Replacement



Total Price: \$220,000.00 USD to Replace



 COC will construct a new door to replace damaged BER (Beyond Economic Repair) door.

NOTE: Cost for honeycomb bonded assembly in quantity of one (1) each is very costly.





COC Lower Fuselage Repair Kit



Total Price: \$80,000.00

Includes:



Overhaul of NWS Actuator



- Complete disassembly, inspection of nose landing gear 14-41600, including strip paint, NDT inspect, anodize, prime and paint.



- Replace damaged parts; cylinder, piston, seals, bushings, hardware, etc.



Inspection of Fuselage Attach Section of Nose Landing Gear



Total Price: \$40,000.00 USD

Includes:





- Inspection of Nose Landing Gear attach points to fuselage including NDT inspection of all key components of fuselage that support the nose landing gear assembly.





Photos of 'AFTER REPAIRS'










Photos of 'AFTER REPAIRS'










Photos of 'AFTER REPAIRS'













The COC F-5 Team - www.coc-aerospace.com



EXPERIENCE - OVER 5 DECADES YEARS SUPPORTING LEGACY AIRCRAFT CUSTOMER SERVICE - OVER 50 YEARSSUPPORTING THE SAME CUSTOMERS TRUST - ABOVE ALL, WE ALWAYS DO THE RIGHT THING



